```
'---------------Title--------------

' File......16F877A_step_mot_half_step.pbp
' Started....2/14/09
' Microcontroller Used:  Microchip Technology 16F877A
'                        microchip.com
' PicBasic Pro Code: micro-Engineering Labs, Inc.
'                    melabs.com
' Stepper Motor Used:  Jameco #237623
' (#237623 - 4.8V, 1500mA, 1.8 Degree Step Angle or 200 Steps/Revolution)

'--------Program Desciption--------

' Program drives stepper motor with 400 steps per revolution.

'------------Schematic-------------

' Use the same schematic as 16F877A_step_mor1.pbp.  See schematic at:
' http://cornerstonerobotics.org/schematics/pic_16f877a_step_mot1.pdf

'----------Related Lesson----------

' See the lesson Stepper Motor Control with a PIC at:
' http://www.cornerstonerobotics.
org/curriculum/lessons_year2/erii_stepper_motor.pdf
' Lesson also includes a section on how to figure out how to hook
' up a stepper motor with six leads when a data sheet for the
' motor is unavailable.

'------------Comments--------------

' WITH THE PIC16F877A, BE CERTAIN TO HAVE SEPARATE POWER
' SOURCES FOR THE PIC AND THE STEPPER MOTOR.  MAKE SURE
' TO HAVE A COMMON GROUND BETWEEN THE PIC AND MOTOR.

'---PicBasic Pro Compiler Manual---

' The PicBasic Pro Compiler Manual is on line at:
' http://www.microengineeringlabs.com/resources/index.htm#Manuals

'---------PIC Connections----------

'     PIC16F877A Pin            Wiring
'       ---------             ----------
'           RB0               Stepper Motor Control Wire 1
'           RB1               Stepper Motor Control Wire 2
'           RB2               Stepper Motor Control Wire 3
'           RB3               Stepper Motor Control Wire 4
'           Vdd               +5 V
'           Vss               Ground
'           MCLR              4.7K Resistor to +5 V

'------------Variables-------------

    Delay   VAR     WORD    ' WORD for variable Delay
```

```
'----------Initialization----------

    TRISB = %00000000       ' Sets all PortB pins to output

'-------------Main Code------------

        Delay = 3           ' Sets Delay varaiable to 3(msec)
                            ' Delay changes the rotational speed
                            ' of the motor. Check for the minimum
                            ' Delay value of your motor.
                            '
                            '  Delay Value    Approx. No-load Current
                            '               Jameco #237623 Stepper Motor
                            ' -------------  -------------------------
                            '      20             1.23 A
                            '      10             1.16 A
                            '       6             0.98 A
                            '       5             1.00 A
                            '       4             0.92 A
                            '       3             0.70 A
                            '       2             0.21 A
                            '       1             Motor Stops Operating
                            '                     Properly
start:

        PORTB = 8           ' Equivalent to PORTB = %00001000
                            ' in binary.  Makes pin RB3 HIGH and all
                            ' other PORTB pins LOW. This sends a
                            ' HIGH signal to the NPN transistor
                            ' connected to pin RB3. The NPN transistor
                            ' grounds one end of the coil connected
                            ' to it, activaing the coil.
                            ' All other coils are off.

        PAUSE Delay         ' PAUSE in milli-seconds so
                            ' PAUSE Delay is a pause of 3(ms)

        PORTB = 12          ' Equivalent to PORTB = %00001100
                            ' in binary.  Makes pin RB3 and RB2 HIGH and
                            ' all other PORTB pins LOW. This sends a
                            ' HIGH signal to the NPN transistors
                            ' connected to pins RB3 & RB2. The NPN
                            ' transistors ground the ends of the coils
                            ' connected to them, activaing those 2 coils.
                            ' All other coils are off.

        PAUSE Delay

        PORTB = 4           ' Equivalent to PORTB = %00000100
                            ' in binary.  Makes pin RB2 HIGH and all
                            ' other PORTB pins LOW. This sends a
                            ' HIGH signal to the NPN transistor
                            ' connected to pin RB2. The NPN transistor
                            ' grounds one end of the coil connected
```

```
                        ' to it, activaing the coil.
                        ' All other coils are off.
PAUSE Delay

PORTB = 6               ' Equivalent to PORTB = %00000110
                        ' in binary.  Makes pin RB2 and RB1 HIGH and
                        ' all other PORTB pins LOW. This sends a
                        ' HIGH signal to the NPN transistors
                        ' connected to pins RB2 & RB1. The NPN
                        ' transistors ground the ends of the coils
                        ' connected to them, activaing those 2 coils.
                        ' All other coils are off.
PAUSE Delay

PORTB = 2               ' Equivalent to PORTB = %00000010
                        ' in binary.  Makes pin RB1 HIGH and all
                        ' other PORTB pins LOW. This sends a
                        ' HIGH signal to the NPN transistor
                        ' connected to pin RB1.
PAUSE Delay

PORTB = 3               ' Equivalent to PORTB = %00000011
                        ' in binary.  Makes pin RB1 and RB0 HIGH and
                        ' all other PORTB pins LOW. This sends a
                        ' HIGH signal to the NPN transistors
                        ' connected to pins RB1 & RB0.
PAUSE Delay

PORTB = 1               ' Equivalent to PORTB = %00000001
                        ' in binary.  Makes pin RB0 HIGH and all
                        ' other PORTB pins LOW. This sends a
                        ' HIGH signal to the NPN transistor
                        ' connected to pin RB0.
PAUSE Delay

PORTB = 9               ' Equivalent to PORTB = %00001001
                        ' in binary.  Makes pin RB3 and RB0 HIGH and
                        ' all other PORTB pins LOW. This sends a
                        ' HIGH signal to the NPN transistors
                        ' connected to pins RB3 & RB0.
PAUSE Delay

GOTO start               ' Start process over again

END
```